

Download 1994 Ford E150 Econoline Van Repair Manual

2000 E150 ford van location of the fuel emerg shut off switch. - Answered by a verified Ford MechanicFord Factory Service Manuals Online. This site provides a detailed review of the ALLDATA DIY product which is an affordable DIY version of the same professional technical data that over 70,000 independent repair shops and dealers use every day.. Only ALLDATA DIY provides instant online access to the complete Ford factory service manual with manufacturer specifications, diagrams, step-by-step ...1994 Ford Truck E150 1/2 ton Van 5.8L MFI 8cyl Temperature Switch is located: Front seating area, center, under engine cover, front driver side of intake manifold, mounted in engine block. The ECT sensor (Engine Coolant Temperature Sensor) is located either in the heater supply tube at the rear of the engine, or in the lower intake manifold.finally! okay I got the sensor and hoses replaced. HOWEVER...there was just one bolt holding the old one on and the other one was missing. the one bolt that was on there was rusted beyond belief. So now I need two bolts to secure the DPFE sensor down and have no idea what size bolts to buy.